

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08194	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Sixshooter Cyn Rd	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08194-2020-05-06-Photo-1.jpg

Description : Roadway ID looking west

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08194	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Sixshooter Cyn Rd	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08194-2020-05-06-Photo-2.jpg

Description : Elevation ID looking Upstream (S)

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08194	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Sixshooter Cyn Rd	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08194-2020-05-06-Photo-3.jpg

Description : Deck Top with AC overlay and rebar exposed on north curb

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08194	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Sixshooter Cyn Rd	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08194-2020-05-06-Photo-4.jpg

Description : Barrel view

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08194	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Sixshooter Cyn Rd	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08194-2020-05-06-Photo-5.jpg

Description : Elevation ID looking downstream (N)

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08194	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Sixshooter Cyn Rd	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08194-2020-05-06-Photo-6.jpg

Description : Exposed rebars on north curb

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08194	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Sixshooter Cyn Rd	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08194-2020-05-06-Photo-7.jpg

Description : Exposed rebars on soffit next to south fascia

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08194	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Sixshooter Cyn Rd	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08194-2020-05-06-Photo-8.jpg

Description : Exposed rebar on outlet headwall