

BRIDGE GROUP

Bridge Maintenance Report

Structure Number :	08197	Structure Name :	Icehouse Canyon Br 2	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Pinal View Drive	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Monday, May 4, 2020
ADOT District:	Southeast			Next Insp. Due By :	May 2022

Work Candidate ID:	BE3E6FD-A2D4-052318-B94E92DF2D	A216 - Actual Completion Cost	\$ <input type="text"/>
Action:	1001 Approach Railing	A215 - Completion Date:	<input type="text"/>
Estimated Quantity:			
Estimated Cost:	\$0.00		
A212 - Repair Priority:	3-Can be scheduled		
Replace missing guardrail spacer block at SW corner.			

Work Candidate ID:	BE3E6FD-EEC0-051320-170DEBDB6B	A216 - Actual Completion Cost	\$ <input type="text"/>
Action:	1001 Approach Railing	A215 - Completion Date:	<input type="text"/>
Estimated Quantity:			
Estimated Cost:	\$0.00		
A212 - Repair Priority:	3-Can be scheduled		
Repair damaged guardrail end section (SE corner) and damaged object markers (SW and SE corners).			

Work Candidate ID:	BE3E6FD-A2D4-052318-A369EFD0CF	A216 - Actual Completion Cost	\$ <input type="text"/>
Action:	1041 Drainage-Repair Washouts / Erosion	A215 - Completion Date:	<input type="text"/>
Estimated Quantity:			
Estimated Cost:	\$0.00		
A212 - Repair Priority:	3-Can be scheduled		
Repair undermining at toe of grouted rock bank protection at NE and SE corners.			