

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08605	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Bixby Road	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08605-2020-05-06-Photo-1.jpg

Description : Roadway ID looking North

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08605	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Bixby Road	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08605-2020-05-06-Photo-10.jpg

Description : Broken off section on southeast corner junction of wingwall and RCB

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08605	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Bixby Road	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08605-2020-05-06-Photo-11.jpg

Description : West side guardrail Damaged

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08605	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Bixby Road	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08605-2020-05-06-Photo-12.jpg

Description : Rebar exposed on floor near outlet.

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08605	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Bixby Road	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08605-2020-05-06-Photo-2.jpg

Description : Elevation ID looking U/S (E)

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08605	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Bixby Road	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08605-2020-05-06-Photo-3.jpg

Description : Deck Top

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08605	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Bixby Road	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08605-2020-05-06-Photo-4.jpg

Description : Barrel View

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08605	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Bixby Road	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08605-2020-05-06-Photo-5.jpg

Description : Bushes encroaching roadway

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08605	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Bixby Road	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08605-2020-05-06-Photo-6.jpg

Description : Rebar exposed at 4th wall from north, at downstream end.

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08605	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Bixby Road	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08605-2020-05-06-Photo-7.jpg

Description : Missing B/Y marker at northeast corner

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08605	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Bixby Road	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08605-2020-05-06-Photo-8.jpg

Description : Guardrail height very low to the ground

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08605	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Bixby Road	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/06/2024



File Name : 08605-2020-05-06-Photo-9.jpg

Description : Inlet gate damaged and debris piled up against inlet gate