

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08914	Structure Name :	Icehouse Canyon Br # 3	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Alamo Way	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Monday, May 4, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/04/2022



File Name : 08914-2020-05-06-Photo-1.jpg

Description : Roadway ID looking West

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08914	Structure Name :	Icehouse Canyon Br # 3	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Alamo Way	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Monday, May 4, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/04/2022



File Name : 08914-2020-05-06-Photo-2.jpg

Description : Elevation ID looking Downstream (N)

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08914	Structure Name :	Icehouse Canyon Br # 3	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Alamo Way	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Monday, May 4, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/04/2022



File Name : 08914-2020-05-06-Photo-3.jpg

Description : Deck Top

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08914	Structure Name :	Icehouse Canyon Br # 3	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Alamo Way	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Monday, May 4, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/04/2022



File Name : 08914-2020-05-06-Photo-4.jpg

Description : Soffit

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08914	Structure Name :	Icehouse Canyon Br # 3	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Alamo Way	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Monday, May 4, 2020
ADOT District:	Southeast			Next Insp. Due By :	05/04/2022



File Name : 08914-2020-05-06-Photo-5.jpg

Description : Elevation ID looking upstream (s)