

**BRIDGE GROUP**

Bridge Inspection Photographs

---

Structure Number :	<b>08197</b>	Structure Name :	<b>Icehouse Canyon Br 2</b>	Inspected by :	<b>ADOT-Zapata/Kazmi</b>
Route :	<b>0</b>	Road Name :	<b>Pinal View Drive</b>	Inspection Type:	<b>Routine</b>
MP :	<b>0</b>	Agency :	<b>Gila Co</b>	Inspection Date :	<b>Monday, May 4, 2020</b>
ADOT District:	<b>Southeast</b>			Next Insp. Due By :	<b>05/04/2022</b>

---



File Name : 08197-2020-05-06-Photo-1.jpg

Description : Roadway ID looking West

### BRIDGE GROUP

#### Bridge Inspection Photographs

---

Structure Number :	<b>08197</b>	Structure Name :	<b>Icehouse Canyon Br 2</b>	Inspected by :	<b>ADOT-Zapata/Kazmi</b>
Route :	<b>0</b>	Road Name :	<b>Pinal View Drive</b>	Inspection Type:	<b>Routine</b>
MP :	<b>0</b>	Agency :	<b>Gila Co</b>	Inspection Date :	<b>Monday, May 4, 2020</b>
ADOT District:	<b>Southeast</b>			Next Insp. Due By :	<b>05/04/2022</b>

---



File Name : 08197-2020-05-06-Photo-2.jpg

Description : Elevation ID looking U/S (S)

**BRIDGE GROUP**

Bridge Inspection Photographs

---

Structure Number :	<b>08197</b>	Structure Name :	<b>Icehouse Canyon Br 2</b>	Inspected by :	<b>ADOT-Zapata/Kazmi</b>
Route :	<b>0</b>	Road Name :	<b>Pinal View Drive</b>	Inspection Type:	<b>Routine</b>
MP :	<b>0</b>	Agency :	<b>Gila Co</b>	Inspection Date :	<b>Monday, May 4, 2020</b>
ADOT District:	<b>Southeast</b>			Next Insp. Due By :	<b>05/04/2022</b>

---



File Name : 08197-2020-05-06-Photo-3.jpg

Description : Deck Top

**BRIDGE GROUP**

Bridge Inspection Photographs

---

Structure Number :	<b>08197</b>	Structure Name :	<b>Icehouse Canyon Br 2</b>	Inspected by :	<b>ADOT-Zapata/Kazmi</b>
Route :	<b>0</b>	Road Name :	<b>Pinal View Drive</b>	Inspection Type:	<b>Routine</b>
MP :	<b>0</b>	Agency :	<b>Gila Co</b>	Inspection Date :	<b>Monday, May 4, 2020</b>
ADOT District:	<b>Southeast</b>			Next Insp. Due By :	<b>05/04/2022</b>

---



File Name : 08197-2020-05-06-Photo-4.jpg

Description : Soffit

**BRIDGE GROUP**

Bridge Inspection Photographs

---

Structure Number :	<b>08197</b>	Structure Name :	<b>Icehouse Canyon Br 2</b>	Inspected by :	<b>ADOT-Zapata/Kazmi</b>
Route :	<b>0</b>	Road Name :	<b>Pinal View Drive</b>	Inspection Type:	<b>Routine</b>
MP :	<b>0</b>	Agency :	<b>Gila Co</b>	Inspection Date :	<b>Monday, May 4, 2020</b>
ADOT District:	<b>Southeast</b>			Next Insp. Due By :	<b>05/04/2022</b>

---



File Name : 08197-2020-05-06-Photo-5.jpg

Description : Northeast slope protection undermined

**BRIDGE GROUP**

Bridge Inspection Photographs

---

Structure Number :	<b>08197</b>	Structure Name :	<b>Icehouse Canyon Br 2</b>	Inspected by :	<b>ADOT-Zapata/Kazmi</b>
Route :	<b>0</b>	Road Name :	<b>Pinal View Drive</b>	Inspection Type:	<b>Routine</b>
MP :	<b>0</b>	Agency :	<b>Gila Co</b>	Inspection Date :	<b>Monday, May 4, 2020</b>
ADOT District:	<b>Southeast</b>			Next Insp. Due By :	<b>05/04/2022</b>

---



File Name : 08197-2020-05-06-Photo-6.jpg

Description : B/Y marker on northeast corner damaged