

BRIDGE GROUP

Bridge Maintenance Report

Structure Number :	08194	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Sixshooter Cyn Rd	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	May 2024

Work Candidate ID: 6135DCD-E947-051020-89DDC93A3A**Action:** 1026 Channel-Remove Debris**Estimated Quantity:****Estimated Cost:****A212 - Repair Priority:** 3-Can be scheduled**A216 - Actual Completion Cost**\$ **A215 - Completion Date:**

Remove debris at inlet wall, see photo 5