

BRIDGE GROUP

Bridge Repair Report

Structure Number :	08194	Structure Name :	Pinal Creek RCB	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Sixshooter Cyn Rd	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	May 2024

Work Candidate ID:	6135DCD-E947-051020-E573942033	A216 - Actual Completion Cost	\$ <input type="text"/>
Action:	2006 Rehab culvert, parapets, approaches		
Estimated Quantity:		A215 - Completion Date:	<input type="text"/>
Estimated Cost:			
A212 - Repair Priority:	3-Can be scheduled		
Patch up and resurface all rebar exposed on this RCB, see photos: 3, 6, 7 and 8			