

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08604	Structure Name :	Pinal Creek Bridge	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Dickison Dr	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Monday, June 1, 2020
ADOT District:	Southeast			Next Insp. Due By :	06/01/2022



File Name : 08604-2020-05-06-Photo-1.jpg

Description : Roadway ID looking North

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08604	Structure Name :	Pinal Creek Bridge	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Dickison Dr	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Monday, June 1, 2020
ADOT District:	Southeast			Next Insp. Due By :	06/01/2022



File Name : 08604-2020-05-06-Photo-2.jpg

Description : Elevation ID looking Upstream (E)

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08604	Structure Name :	Pinal Creek Bridge	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Dickison Dr	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Monday, June 1, 2020
ADOT District:	Southeast			Next Insp. Due By :	06/01/2022



File Name : 08604-2020-05-06-Photo-3.jpg

Description : Deck Top

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08604	Structure Name :	Pinal Creek Bridge	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Dickison Dr	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Monday, June 1, 2020
ADOT District:	Southeast			Next Insp. Due By :	06/01/2022



File Name : 08604-2020-05-06-Photo-4.jpg

Description : Soffit

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08604	Structure Name :	Pinal Creek Bridge	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Dickison Dr	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Monday, June 1, 2020
ADOT District:	Southeast			Next Insp. Due By :	06/01/2022



File Name : 08604-2020-05-06-Photo-5.jpg

Description : Erosion on northeast corner of Bridge

BRIDGE GROUP

Bridge Inspection Photographs

Structure Number :	08604	Structure Name :	Pinal Creek Bridge	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Dickison Dr	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Monday, June 1, 2020
ADOT District:	Southeast			Next Insp. Due By :	06/01/2022



File Name : 08604-2020-05-06-Photo-6.jpg

Description : South abutment tilt