

BRIDGE GROUP

Bridge Maintenance Report

Structure Number :	08706	Structure Name :	Pinal Creek Bridge	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Hicks Road	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Wednesday, May 6, 2020
ADOT District:	Southeast			Next Insp. Due By :	May 2022

Work Candidate ID: 703588C-9FDC-051220-1AACC45966**Action:** 1056 Misc-Remove Vegetation**Estimated Quantity:****Estimated Cost:** \$0.00**A212 - Repair Priority:** 1-Immediate action req**A216 - Actual Completion Cost**\$ **A215 - Completion Date:**

Cut bushes encroaching several shoulder areas.