

BRIDGE GROUP

Bridge Maintenance Report

Structure Number :	08198	Structure Name :	Icehouse Canyon Br 1	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Albany Dr.	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Monday, May 4, 2020
ADOT District:	Southeast			Next Insp. Due By :	May 2022

Work Candidate ID:	9651C46-985B-052318-ACF0937859	A216 - Actual Completion Cost	\$ <input type="text"/>
Action:	1027 Channel-Repair Washouts / Erosion		
Estimated Quantity:		A215 - Completion Date:	<input type="text"/>
Estimated Cost:	\$0.00		
A212 - Repair Priority:	3-Can be scheduled		

Repair undermined grouted rock apron.