

**BRIDGE GROUP**

Bridge Maintenance Report

Structure Number :	<b>08605</b>	Structure Name :	<b>Pinal Creek RCB</b>	Inspected by :	<b>ADOT-Zapata/Kazmi</b>
Route :	<b>0</b>	Road Name :	<b>Bixby Road</b>	Inspection Type:	<b>Routine</b>
MP :	<b>0</b>	Agency :	<b>Gila Co</b>	Inspection Date :	<b>Wednesday, May 6, 2020</b>
ADOT District:	<b>Southeast</b>			Next Insp. Due By :	<b>May 2024</b>

<b>Work Candidate ID:</b>	36DAEEB-C789-051020-970D5C37EC	<b>A216 - Actual Completion Cost</b>	\$ <input type="text"/>
<b>Action:</b>	2006 Rehab culvert, parapets, approaches	<b>A215 - Completion Date:</b>	<input type="text"/>
<b>Estimated Quantity:</b>			
<b>Estimated Cost:</b>	\$0.00		
<b>A212 - Repair Priority:</b>	3-Can be scheduled		

Patch up and resurface all rebar exposed, spalls and large cracking. See photo 6, 10 and 12.

<b>Work Candidate ID:</b>	36DAEEB-C789-051020-54DCF0817A	<b>A216 - Actual Completion Cost</b>	\$ <input type="text"/>
<b>Action:</b>	1001 Approach Railing	<b>A215 - Completion Date:</b>	<input type="text"/>
<b>Estimated Quantity:</b>			
<b>Estimated Cost:</b>	\$0.00		
<b>A212 - Repair Priority:</b>	3-Can be scheduled		

Increase height and repair guardrail at all damaged areas. See photo 1, 7,8 and 11.

<b>Work Candidate ID:</b>	36DAEEB-C789-051020-BF342D3B5F	<b>A216 - Actual Completion Cost</b>	\$ <input type="text"/>
<b>Action:</b>	1056 Misc-Remove Vegetation	<b>A215 - Completion Date:</b>	<input type="text"/>
<b>Estimated Quantity:</b>			
<b>Estimated Cost:</b>	\$0.00		
<b>A212 - Repair Priority:</b>	3-Can be scheduled		

Remove trees and bushes from roadway. See photo 5.

<b>Work Candidate ID:</b>	36DAEEB-C789-051020-D721201475	<b>A216 - Actual Completion Cost</b>	\$ <input type="text"/>
<b>Action:</b>	1026 Channel-Remove Debris	<b>A215 - Completion Date:</b>	<input type="text"/>
<b>Estimated Quantity:</b>			
<b>Estimated Cost:</b>	\$0.00		
<b>A212 - Repair Priority:</b>	3-Can be scheduled		

Reinstall gates at right of way and remove debris build up at inlet, see photo 9.

<b>Work Candidate ID:</b>	36DAEEB-C789-051020-548329E4BC	<b>A216 - Actual Completion Cost</b>	\$ <input type="text"/>
<b>Action:</b>	1053 Misc-Install Sign	<b>A215 - Completion Date:</b>	<input type="text"/>
<b>Estimated Quantity:</b>			
<b>Estimated Cost:</b>	\$0.00		
<b>A212 - Repair Priority:</b>	3-Can be scheduled		

Install B/Y Object marker on NE corner. See photo 7.