

BRIDGE GROUP

Bridge Maintenance Report

Structure Number :	08914	Structure Name :	Icehouse Canyon Br # 3	Inspected by :	ADOT-Zapata/Kazmi
Route :	0	Road Name :	Alamo Way	Inspection Type:	Routine
MP :	0	Agency :	Gila Co	Inspection Date :	Monday, May 4, 2020
ADOT District:	Southeast			Next Insp. Due By :	May 2022

Work Candidate ID: AE256DA-2BA1-051320-1023B0EA19**Action:** 1027 Channel-Repair Washouts / Erosion**Estimated Quantity:****Estimated Cost:** \$0.00**A212 - Repair Priority:** 3-Can be scheduled**A216 - Actual Completion Cost**\$ **A215 - Completion Date:**

Repair some undermining under the grouted rock apron at the outlet.